


CLIENT: LUXOTTICA GROUP S.p.A.  
 PERIOD: 2018  
 LOCATION: MILAN - LINATE (ITALY)  
 DESCRIPTION: 3,000 m<sup>2</sup>  
 SERVICES PROVIDED: DUE DILIGENCE TECHNICAL REPORT




GENERAL VIEW OF THE ROOF




ANALYSIS OF PROJECT DOCUMENTATION AND STATE OF THE PLACES RELATED TO THE SEALING OF THE ROOF OF THE NEW HANGAR AT THE GENERAL AIRPORT OF MILAN - LINATE



ROOF PLAN  
 IDENTIFICATION OF INFILTRATION ZONES  
 ON THE UNDERLYING FLOOR



SECTION WITH IDENTIFICATION OF  
 WASHED OUT WALLS



PHOTOGRAPHIES  
 OF THE ZONES  
 WITH  
 WATER STAGNATION



**DUE DILIGENCE**